

To: Barry, Michael[Barry.Michael@epa.gov]
From: Grantham, Nancy
Sent: Wed 9/30/2015 2:49:30 PM
Subject: RE: La Plata County GKM Adit Sampling Event week of 9/28

I think she is looking for when our sampling results (ones we took before theirs) would be ready
thanks n g

From: Barry, Michael
Sent: Wednesday, September 30, 2015 10:49 AM
To: Sheryl Rogers <rogers@lpcattorney.org>; Matt DeAmico <mdeamico@wrightwater.com>
Cc: Grantham, Nancy <Grantham.Nancy@epa.gov>; Joe Kerby <Joe.Kerby@co.laplate.co.us>;
Joanne Spina <Joanne.Spina@co.laplate.co.us>; Jenkins, Laura Flynn
<Jenkins.Laura@epa.gov>; Ostrander, David <Ostrander.David@epa.gov>; Peter Foster
<pfoster@wrightwater.com>; Jakoby Leslie <Leslie.Jakoby@co.laplate.co.us>; Trevor Downing
<tdowning@wrightwater.com>; Kari Lanphier <klanphier@wrightwater.com>
Subject: RE: La Plata County GKM Adit Sampling Event week of 9/28

You're welcome Sheryl.

I'll defer to Matt on answering when the results will be available from Wright Water
Engineering's contracted lab.

Thanks,

Mike

Mike Barry | Cell: 617.680.5466 | barry.michael@epa.gov

9/24 – 10/7/2015:

Incident Commander

Gold King Mine Response

Durango, CO

Permanent:

Team Leader On-Scene Coordinator,
Emergency Response & Planning Branch

EPA Region 1, 5 Post Office Square, Suite 100 (OSRR02-2), Boston, MA, 02109

From: Sheryl Rogers [<mailto:rogers@lpcattorney.org>]
Sent: Wednesday, September 30, 2015 7:52 AM
To: Barry, Michael <Barry.Michael@epa.gov>; Matt DeAmico <mdeamico@wrightwater.com>
Cc: Grantham, Nancy <Grantham.Nancy@epa.gov>; Joe Kerby <Joe.Kerby@co.laplata.co.us>;
Joanne Spina <Joanne.Spina@co.laplata.co.us>; Jenkins, Laura Flynn
<Jenkins.Laura@epa.gov>; Ostrander, David <Ostrander.David@epa.gov>; Peter Foster
<pfoster@wrightwater.com>; Jakoby Leslie <Leslie.Jakoby@co.laplata.co.us>; Trevor Downing
<tdowning@wrightwater.com>; Kari Lanphier <klanphier@wrightwater.com>
Subject: RE: La Plata County GKM Adit Sampling Event week of 9/28

Thanks to all of you for accommodating La Plata County's sampling last night. Can EPA please tell me when the results of its sampling for the additional constituents will be available to the County?

Sheryl1

From: Barry, Michael [<mailto:Barry.Michael@epa.gov>]
Sent: Thursday, September 24, 2015 6:53 PM
To: Matt DeAmico <mdeamico@wrightwater.com>; Sheryl Rogers <rogers@lpcattorney.org>
Cc: Grantham, Nancy <Grantham.Nancy@epa.gov>; Joe Kerby <Joe.Kerby@co.laplata.co.us>;
Joanne Spina <Joanne.Spina@co.laplata.co.us>; Jenkins, Laura Flynn
<Jenkins.Laura@epa.gov>; Ostrander, David <Ostrander.David@epa.gov>; Peter Foster
<pfoster@wrightwater.com>; Jakoby Leslie <Leslie.Jakoby@co.laplata.co.us>; Trevor Downing
<tdowning@wrightwater.com>; Kari Lanphier <klanphier@wrightwater.com>
Subject: La Plata County GKM Adit Sampling Event week of 9/28

Hi Sheryl and Matt,

EPA is pleased to offer Tuesday, 9/29, at 5 pm to support La Plata County/Wright Water Engineer's sampling of mine water from the GKM Adit. Does this work for you?

We understand that Wright Water Engineer's will provide all sampling containers, apparatus, etc. And will be sending the samples for analysis to a lab of it's arrangement and cost. Please let us know if that isn't correct. EPA or EPA contractors will provide transport from the Gladstone Command Post, site escorts and safety monitors. EPA also indents to drawl samples for the constituents whose hold times were not meet in the sampling last week. Samples should be drawn from mutually agreed upon locations by field personnel, upstream of where shotcrete operations have occurred as far as possible, given safety and access considerations.

Logistics:

Please have personnel arrive at the Gladstone Command Post to be ready to be transported to the GKM Adit by approximately 4:30-4:45 pm. Personnel should have Level D gear (safety shoes, hard hat, orange or yellow safety vest and safety glasses) in addition to any PPE for sampling. Note that active work for the day will have concluded at this time.

Please provide the number of personnel & approx. amount of equipment needed to transport.

Gladstone Command Post Points of Contact.

Command Post Watch Line: 303.954.4719 (this is the best way to contact)

POC: Steve Way, cell: 303 886.1640

Thank You

Mike

Mike Barry | Cell: 617.680.5466 | barry.michael@epa.gov

9/24 to 10/7 2015

Incident Commander

Gold King Mine Response

Durango, CO

Permanent:

Team Leader On-Scene Coordinator,

Emergency Response & Planning Branch

EPA Region 1, 5 Post Office Square, Suite 100 (OSRR02-2), Boston, MA, 02109